

Project #	Date Requested	Address/Site Location	CD	Improvement	Estimate	Status	Date Completed	Actual ARP	Other Funds	Notes
24-12 SEE 24-	1/23/2024	360 Mira Mar	3	Sidewalk						Very uneven sidewalk, probably due to tree roots.
24-13	1/23/2024	317 Loma Ave. 90814	3	Sidewalk						uneven sidewalk as a result of tree roots. affected area spreads to the street and curb as well.
24-14	1/25/2024	763 Loma Ave.	3	Sidewalk						Severely cracked sidewalk causing wide gaps and an uneven surface.
24-15	1/26/2024	345 E. 59th Street	9	Sidewalk						sidewalk lifting due to tree roots growing.
24-16	1/26/2024	389, 360, 356, 333, 325 and 301 Mira Mar Ave.	3	Sidewalk						multiple areas where tree roots are causing major uplift of sidewalks.
24-17	1/26/2024	239 and 237 Euclid Ave., 90803	3	Sidewalk						crooked sidewalk in front of both locations
24-18	1/26/2024	3723 and 3518 E. Vista, 90803	3	Sidewalk						crooked sidewalk in front of both locations
24-19	2/2/2024	1913, 1919, 1960, 1985 Lime Ave., 90806	6	Sidewalk						cracked and raised areas of sidewalk
24-20	3/4/2024	3014 Karen Avenue, 90808	4	Sidewalk						sidewalk
24-21	3/4/2024	1001, 1008, 1011, 1012, 1018, 1024, 1048, 1054,	8	Sidewalk						uneven and sunken sidewalk in many areas of the block, some areas look like patching could be helpful.
24-22	3/4/2024	5709 E. Oakbrook Street, 90815	4	Sidewalk						south side of the residence - uneven curb what seems to be caused by tree roots.
24-23	3/9/2024	2009, 2000, 2014, 2110, 2118, 2124, 2276, 2215, 2203, 2071 Easy Ave., 90810	7	Sidewalk						Multiple locations need patching or complete new sidewalk as a result of tree roots making sidewalk uneven.
24-24	3/9/2024	PCH between Caspian and Harbor	7	Sidewalk						There is an area at the bus stop on the N side of PCH between Caspian Ave. and Harbor Blvd. that is crooked, and on the same side of the street near the auto mechanic - sidewalk is difficult to traverse.
24-25	3/12/2024	2209 Clark Ave., 90815	4	parklet						resident has a physical disability and requesting dirt parklet be replaced with concrete.