STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8501

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1046	34	06D191151OA2220	.100	21		.096			X		PARILLA	17332	9

01/04/07 10:48
PAS Serial no: 000501
Version no: 4797

No.	Date	Time	ZBAC
Calibration	10/07/04	09:33	.100

Test	Result		
0001	12/30/06	00:36	.151
0002	12/30/06	00:37	.151
0003	01/01/07	02:16	.061
0004	01/01/07	02:17	.069
0005	01/01/07	02:44	.067
0006	01/01/07	02:45	.061
0007	01/01/07	02:48	.120
0008	01/01/07	02:50	.023
0009	01/04/07	10:47	.098

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH. LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	850X

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1102	34	06D191151OA2220	.100	23		.102			X		PARILLA	17332	/

01/04/07 11:24
AS4 Serial no: 008550
Version no: 4797

No. Date Time %BAC
Calibration
12/01/06 08:14 .099

Test Result
0001 01/04/07 11:23 .102

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8546

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1343	34	060191151OA2220	.100	23							PARILLA	17332	7

```
01/04/07 13:44
ASA Serial no: 008546
Version    no: 4797

No.  Date     Time  %BAC
Calibration
     04/22/04 07:47 .100

Test Result
0001 01/01/07 01:33 .079
0002 01/01/07 01:36 .079
0003 01/01/07 02:08 .000
0004 01/01/07 02:56 .039
0005 01/01/07 03:28 .165
0006 01/01/07 08:31 .151
0007 01/04/07 13:44 .100

Push No. 3 to erase,
or power down to retain
```

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	6554

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1108	34	06D1911510A2220	.100	21		.103			X		PARILLA	17332	7

01/04/07 11:11
ASA Serial no: 008559
Version no: 4797

No.	Date	Time	%BAC
Calibration	10/25/05	07:58	.100

Test	Result		
0001	12/30/06	02:40	.102
0002	12/30/06	02:42	.098
0003	12/31/06	01:32	.160
0004	12/31/06	01:34	.151
0005	01/01/07	19:34	.181
0006	01/01/07	19:36	.184
0007	01/04/07	11:09	.103

Push No. 3 to erase,
or Power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH. LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8620

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1142	34	06D1911510A2220	.100	22		.106			x		PARILLA	17332	2

01/04/07 11:43
ASA Serial no: 008620
Version no: 4797

No.	Date	Time	%BAC
Calibration	05/26/05	09:25	.100

Test Result			
0001	12/29/06	00:32	.025
0002	01/04/07	11:42	.106

Push No. 3 to erase.
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8635

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1233	34	06D1911510A2220	.100	22		.103			X		PARILLA	17332	1

01/04/07 12:34
AS4 Serial no: 008877
Version no: 4797

No. Date Time %BAC
Calibration
05/26/05 10:40 .100

Test Result
0001 01/04/07 12:33 .103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	86463

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1145	34	06D191151OA2220	.100	22		.105			X		PARILLA	17332	28

01/04/07 11:46
AS4 Serial no: 008663
Version no: 4797

No. Date Time %BAC
Calibration
12/21/04 11:26 .100

Test Result

0001	12/29/06	00:44	.023
0002	12/29/06	01:52	.114
0003	12/29/06	01:54	.114
0004	12/29/06	03:39	.046
0005	12/29/06	22:45	.000
0006	12/30/06	00:33	.079
0007	12/30/06	00:35	.075
0008	12/30/06	00:49	.150
0009	12/30/06	00:51	.127
0010	12/30/06	00:53	.163
0011	12/30/06	01:48	.000
0012	12/30/06	02:10	.134
0013	12/30/06	02:12	.137
0014	12/31/06	00:16	.000
0015	12/31/06	00:51	.122
0016	12/31/06	00:53	.123
0017	12/31/06	02:20	.091
0018	12/31/06	02:30	.085
0019	12/31/06	21:49	.132
0020	[illegible]	21:51	.151
0021	01/01/07	00:07	.038
0022	01/01/07	00:32	.000
0023	01/01/07	00:47	.029
0024	01/01/07	01:07	.000
0025	01/01/07	03:29	.121
0026	01/01/07	03:31	.120
0027	01/01/07	03:54	.063
0028	01/04/07	11:46	.105

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8709

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1158	34	060191151 0A2220	.100	22		.097			X		PARILLA	17332	9

01/04/07 11:59
HS4 Serial no: 008709
Version no: 4797

No.	Date	Time	%BAC
Calibration	05/20/04	11:06	.096
Test Result			
0001	01/01/07	00:37	.000
0002	01/01/07	01:19	.000
0003	01/01/07	01:20	.000
0004	01/01/07	01:30	.000
0005	01/01/07	01:55	.102
0006	01/01/07	01:56	.098
0007	01/02/07	01:41	.031
0008	01/02/07	01:42	.028
0009	01/04/07	11:58	.097

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH. LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8714

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1220	34	060191151OA2220	.100	22		.102			x		PARILLA	17332	4

01/04/07 12:21
AS4 Serial no: 008714
Version no: 4797

No. Date Time %BAC
Calibration
03/11/04 14:05 .100

Test Result
0001 01/01/07 02:58 .178
0002 01/01/07 03:00 .177
0003 01/02/07 06:33 .000
0004 01/04/07 12:20 .102

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH. LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8783

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION TEMP (°C)	SIMULATOR SOLUTION LOT NO.	SIMULATOR SOLUTION VALUE	PAS TEMP (°C) TEST #1	PAS TEMP (°C) TEST #2 (Optional)	PAS ACCURACY CHECK RESULTS* TEST #1	PAS ACCURACY CHECK RESULTS* TEST #2 (Optional)	CALIBRATION REQUIRED YES	CALIBRATION REQUIRED NO	PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
01 04 07	1229	34	060191151 0A2220	.100	21		.106					PARILLA	17332	19

01/04/07 12:31
AS4 Serial no: 008783
Version no: 4797

No. Date Time %BAC
Calibration
10/17/06 09:36 .102

Test Result
0001 12/23/06 00:33 .231
0002 12/23/06 00:35 .217
0003 12/23/06 02:33 .141
0004 12/23/06 02:34 .150
0005 12/23/06 02:58 .230
0006 12/23/06 03:01 .224
0007 12/29/06 16:34 .000
0008 12/30/06 01:03 .083
0009 12/30/06 01:04 .080
0010 12/30/06 03:09 .083
0011 12/30/06 03:11 .088
0012 12/31/06 00:00 .000
0013 12/31/06 02:18 .020
0014 12/31/06 02:49 .144
0015 12/31/06 02:50 .147
0016 01/01/07 23:26 .189
0017 01/01/07 23:27 .211
0018 01/01/07 20:29 .219
0019 01/04/07 12:29 .106

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH. LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8810

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1286	34	06D191151OA2220	.100	22		.097			X		PARILLA	17332	1

01/04/07 12:39
AS4 Serial no: 008810
Version no: 4797

No.	Date	Time	%BAC
Calibration	10/30/03	09:53	.100

Test Result
0001 01/04/07 12:39 .097

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8845

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1337	34	060191151 0A2220	.100	24		.101			X		PARILLA	17332	8

01/04/07 13:39
AS4 Serial no: 008845
Version no: 4797

No.	Date	Time	%BAC
Calibration	12/24/03	11:01	.100

Test Result

0001	12/30/06	06:39	.110
0002	12/30/06	06:40	.101
0003	12/31/06	07:16	.100
0004	12/31/06	07:25	.087
0005	12/31/06	07:26	.090
0006	01/01/07	09:24	.000
0007	01/01/07	09:25	.000
0008	01/04/07	13:38	.101

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	8848

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1316	34	0001911510A2222	.100	22		.093			X		PARILLA	17332	22

01/04/07 13:47
ASA Serial no: 008848
Version no: 4797

No.	Date	Time	%BAC
Calibration			
	01/13/03	09:25	.100
Test Result			
0001	12/28/06	22:37	.065
0002	12/28/06	22:39	.075
0003	12/28/06	22:41	.000
0004	12/29/06	02:32	.123
0005	12/29/06	02:34	.113
0006	12/31/06	22:18	.069
0007	12/31/06	22:12	.085
0008	12/31/06	22:13	.167
0009	12/31/06	22:14	.048
0010	12/31/06	22:16	.112
0011	12/31/06	22:17	.218
0012	12/31/06	22:19	.169
0013	12/31/06	22:20	.035
0014	12/31/06	22:21	.077
0015	12/31/06	22:22	.015
0016	12/31/06	22:25	.076
0017	12/31/06	22:26	.101
0018	01/01/07	03:42	.083
0019	01/01/07	03:57	.000
0020	01/03/07	02:35	.000
0021	01/03/07	23:06	.044
0022	01/04/07	13:46	.093

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO SENSOR IV	8850

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1357	34	06D1911510A2220	.100	22		.100			✓		PARILLA	17332	7

01/04/07 13:52
PAS Serial no: 008850
Version no: 4797

No.	Date	Time	%BAC
Calibration	03/02/06	09:07	.100

Test Result

0001	12/29/06	23:21	.155
0002	12/29/06	23:24	.167
0003	12/31/06	01:48	.124
0004	12/31/06	01:51	.129
0005	01/04/07	01:26	.166
0006	01/04/07	01:21	.172
0007	01/04/07	13:51	.100

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 005

AREA NAME: SOUTH LOS ANGELES
AREA NO.: 530
COORDINATOR NAME: PARILLA
ID NUMBER: 17332
PAS MAKE/MODEL: ALCO-SENSOR IV
PAS SERIAL NO.: 018624

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	TEMP (°C)	SIMULATOR SOLUTION LOT NO	SIMULATOR SOLUTION VALUE	TEST #1	TEST #2 (Optional)	PAS TEMP (°C)	PAS ACCURACY CHECK RESULTS TEST #1	TEST #2 (Optional)	CALIBRATION REQUIRED YES	CALIBRATION REQUIRED NO	PAS RETEST RESULTS	OPERATOR ID NO	REPAIR PROBLEM COMMENTS
01 04 07	1454	34	06	19	15	08	22	.103	.123		✓		PAR LA	17232

01/04/07 14:55
AS4 Serial no: 018624
Version no: 4797

No.	Date	Time	%BAC
Calibration			
	05/01/03	05:38	.100
Test Result			
0001	12/01/06	00:11	.112
0002	12/01/06	00:13	.120
0003	12/01/06	02:54	.079
0004	12/01/06	02:55	.079
0005	12/01/06	03:10	.079
0006	12/01/06	03:15	.090
0007	12/02/06	00:37	.025
0008	12/02/06	00:38	.025
0009	12/02/06	01:43	.000
0010	12/02/06	01:44	.000
0011	12/02/06	02:26	.000
0012	12/02/06	02:27	.000
0013	12/02/06	02:41	.000
0014	12/02/06	02:42	.000
0015	12/02/06	02:59	.230
0016	12/02/06	03:01	.191
0017	12/02/06	04:56	.092
0018	12/02/06	04:57	.097
0019	12/04/06	21:59	.127
0020	12/04/06	22:01	.138
0021	12/04/06	22:34	.160
0022	12/04/06	22:36	.171
0023	12/06/06	01:00	.107
0024	12/06/06	01:02	.111
0025	12/14/06	01:01	.072
0026	12/14/06	02:20	.232
0027	12/14/06	02:22	.236
0028	12/16/06	00:36	.161
0029	12/16/06	00:37	.154
0030	12/20/06	01:05	.169
0031	12/20/06	01:06	.162
0032	12/22/06	03:15	.147
0033	12/22/06	03:17	.146
0034	12/24/06	22:28	.267
0035	12/24/06	22:29	.278
0036	01/04/07	14:54	.103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	17990

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION TEMP (°C)	SIMULATOR SOLUTION LOT NO	SIMULATOR SOLUTION VALUE	PAS TEMP (°C) TEST #1	PAS TEMP (°C) TEST #2 (Optional)	PAS ACCURACY CHECK RESULTS* TEST #1	PAS ACCURACY CHECK RESULTS* TEST #2 (Optional)	CALIBRATION REQUIRED YES	CALIBRATION REQUIRED NO	PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/COMMENTS
01 04 07	1438	34	06D1911510A2220	.100	22		.102			X		PARILLA	17332	1

01/04/07 14:39
AS4 Serial no: 017990
Version no: 4797

No. Date Time %BAC
Calibration
11/26/03 11:10 .100

Test Result
0001 01/04/07 14:39 .102

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 8-98) OPI 005

AREA NAME: SOUTH LOS ANGELES
AREA NO: 630
COORDINATOR NAME: PARILLA
ID NUMBER: 17332
PAS MAKE/MODEL: ALCO SENSOR IV
PAS SERIAL NO: 18424

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	TEMP (°C)	SIMULATOR SOLUTION LOT NO	SIMULATOR SOLUTION VALUE	PAS TEMP (°C)	PAS ACCURACY CHECK RESULTS TEST #1	PAS ACCURACY CHECK RESULTS TEST #2 (Optional)	CALIBRATION REQUIRED YES	CALIBRATION REQUIRED NO	PAS RETEST RESULTS	OPERATOR	ID NO	REPAIR/PROBLEMS COMMENTS
01/04/07	1454	34	06P191150R2222	.100	23	.103			X		PARILLA	17332	34

01/04/07 14:55
AS4 Serial no: 018624
Version no: 4797

No. Date Time %BAC
Calibration
05/01/03 05:38 .100

Test Result
0001 12/01/06 00:11 .112
0002 12/01/06 00:13 .120
0003 12/01/06 02:54 .079
0004 12/01/06 02:55 .079
0005 12/01/06 03:10 .079
0006 12/01/06 03:15 .090
0007 12/02/06 00:37 .025
0008 12/02/06 00:38 .025
0009 12/02/06 01:43 .000
0010 12/02/06 01:44 .000
0011 12/02/06 02:26 .000
0012 12/02/06 02:27 .000
0013 12/02/06 02:41 .000
0014 12/02/06 02:42 .000
0015 12/02/06 02:59 .230
0016 12/02/06 03:01 .191
0017 12/02/06 04:56 .092
0018 12/02/06 04:57 .097
0019 12/04/06 21:59 .127
0020 12/04/06 22:01 .138
0021 12/04/06 22:34 .160
0022 12/04/06 22:36 .171
0023 12/06/06 01:00 .107
0024 12/06/06 01:02 .111
0025 12/14/06 01:01 .072
0026 12/14/06 02:20 .232
0027 12/14/06 02:22 .236
0028 12/16/06 00:36 .161
0029 12/16/06 00:37 .154
0030 12/20/06 01:05 .169
0031 12/20/06 01:06 .162
0032 12/22/06 03:15 .147
0033 12/22/06 03:17 .146
0034 12/24/06 22:28 .267
0035 12/24/06 22:29 .278
0036 01/04/07 14:54 .103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	18646

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1340	34	060191151 0A2220	.100	24		.098			X		PARILLA	17332	3

01/04/07 13:41
AS4 Serial no: 018646
Version no: 4797

No.	Date	Time	%BAC
Calibration	06/10/04	12:18	.100

Test Result			
0001	01/01/07	15:51	.200
0002	01/01/07	15:53	.261
0003	01/04/07	13:40	.098

Push No. 3 to erase
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	18689

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

		SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED					
DATE	TIME	TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO	PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
01 04 07	1444	34	060191150A2205	.100	24		.102			X		PARILLA	17332	/

01/04/07 14:45
ASA Serial no: 018684
Version no: 4797
No. Date Time ?BAC
Calibration
01/29/04 12:45 .100
Test Result
0001 01/04/07 14:45 .102
Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH. LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	18691

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1240	34	060191151 0A2220	.100	22		.101			X		PARILLA	17332	

01/04/07 12:42
AS4 Serial no: 008635
Version no: 4797

No.	Date	Time	%BAC
Calibration	10/24/03	09:04	.100

Test Result
0001 01/04/07 12:41 .101

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH. LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	1869

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1236	34	06D191151OA2220	.100	23		.106			X		PARILLA	17332	1

01/04/07 12:37
AS4 Serial no: 018691
Version no: 4797

No. Date Time %BAC
Calibration
01/28/06 08:44 .100

Test Result
0001 01/04/07 12:37 .106

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	18762

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1425	34	06D191151OA2220	.100	21		.105			X		PARILLA	17332	

01/04/07 14:30
AS4 Serial no: 018762
Version no: 4797

No.	Date	Time	%BAC
Calibration			
	03/11/04	15:53	.100

Test Result
0001 01/04/07 14:29 .105

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	18766

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1425	34	06D191151OA2220	.100	21		~~.14~~ .101			X		PARILLA	17332	3

01/04/07 14:26
AS4 Serial no: 018766
Version no: 4797

No.	Date	Time	%BAC
Calibration	12/09/02	09:55	.100

Test Result			
0001	12/31/06	20:50	.167
0002	12/31/06	20:52	.148
0003	01/04/07	14:25	.101

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-95) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	18774

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION TEMP (°C)	SIMULATOR SOLUTION LOT NO.	SIMULATOR SOLUTION VALUE	PAS TEMP (°C) TEST #1	PAS TEMP (°C) TEST #2 (Optional)	PAS ACCURACY CHECK RESULTS* TEST #1	PAS ACCURACY CHECK RESULTS* TEST #2 (Optional)	CALIBRATION REQUIRED YES	CALIBRATION REQUIRED NO	PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/COMMENTS
01 04 07	1441	34	06D1911510A2220	.100	21		.102			X		PARILLA	17332	1

01/04/07 14:45
AS4 Serial no: 018774
Version no: 4797

No. Date Time %BAC
Calibration
06/01/06 16:42 .100

Test Result
0001 01/04/07 14:45 .102

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	18785

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01 04 07	1050	34	06D1911510A2220	.100	21		.101			X		PARILLA	17332	13

01/04/07 10:52
AS4 Serial no: 018785
Version no: 4797

No. Date Time %BAC
Calibration
11/03/05 09:34 .100

Test Result
0001 12/29/06 02:08 .150
0002 12/29/06 02:10 .231
0003 12/29/06 02:12 .220
0004 12/29/06 03:06 .178
0005 12/29/06 03:07 .185
0006 12/30/06 01:39 .179
0007 12/30/06 01:40 .167
0008 12/31/06 03:04 .178
0009 12/31/06 03:06 .198
0010 01/01/07 12:48 .129
0011 01/01/07 12:57 .139
0012 01/01/07 12:59 .132
0013 01/04/07 10:51 .101

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-95) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	ID NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO SENSOR IV	41486

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION TEMP (°C)	SIMULATOR SOLUTION LOT NO	SIMULATOR SOLUTION VALUE	PAS TEMP (°C) TEST #1	PAS TEMP (°C) TEST #2 (Optional)	PAS ACCURACY CHECK RESULTS* TEST #1	PAS ACCURACY CHECK RESULTS* TEST #2 (Optional)	CALIBRATION REQUIRED YES	CALIBRATION REQUIRED NO	PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
01 04 07	1500	34	060911510A2225	.100	26		.103			✓		PARILLA	17332	2

01/04/07 15:01
AS4 Serial no: 041486
Version no: 4797

No.	Date	Time	ZBAC
Calibration	03/08/06	13:56	.100

	Test Result		
0001	12/15/06	17:15	.107
0002	01/04/07	15:00	.103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 061

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO SENSOR IV	41559

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION TEMP (°C)	SIMULATOR SOLUTION LOT NO.	SIMULATOR SOLUTION VALUE	PAS TEMP (°C) TEST #1	PAS TEMP (°C) TEST #2 (Optional)	PAS ACCURACY CHECK RESULTS TEST #1	PAS ACCURACY CHECK RESULTS TEST #2 (Optional)	CALIBRATION REQUIRED YES	CALIBRATION REQUIRED NO	PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/COMMENTS
01 04 07	1510	34	06D191510A2220	.100	21		.099			X		PARILLA	17332	7

01/04/07 15:11
AS4 Serial no: 041559
Version no: 4797

No. Date Time ZBAC
Calibration
11/02/05 14:35 .102

Test Result
0001 12/30/06 01:25 .108
0002 12/30/06 01:28 .102
0003 12/31/06 01:41 .185
0004 12/31/06 01:44 .157
0005 12/31/06 01:46 .179
0006 01/01/07 02:46 .063
0007 01/04/07 15:10 .099

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 081

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
SOUTH LOS ANGELES	530	PARILLA	17332	ALCO-SENSOR IV	41495

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION TEMP (°C)	SIMULATOR SOLUTION LOT NO	SIMULATOR SOLUTION VALUE	PAS TEMP (°C) TEST #1	PAS TEMP (°C) TEST #2 (Optional)	PAS ACCURACY CHECK RESULTS* TEST #1	PAS ACCURACY CHECK RESULTS* TEST #2 (Optional)	CALIBRATION REQUIRED YES	CALIBRATION REQUIRED NO	PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
01/04/07	1530	34	06D19157OA2220	.100	96		.097			X		PARILLA	17332	

01/04/07 14:57
ASA Serial no: 041495
Version no: 4297

No.	Date	Time	ZEAC
Calibration	12/01/06	08:23	.099

Test Result

0001	12/23/06	01:37	.187
0002	12/23/06	01:39	.172
0003	12/24/06	00:38	.343
0004	12/24/06	00:41	.295
0005	12/24/06	00:43	.324
0006	12/25/06	02:39	.191
0007	12/25/06	02:42	.187
0008	01/01/07	02:17	.000
0009	01/04/07	14:56	.097

Push No. 3 to erase,
or Power down to retain