#1

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	ID NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8501

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1148	34	06D1911510A2220	.100	22		.100			x		Parilla	17332	8

01/11/07 11:49
RBA Serial no: 008501
Version no: 4797

No.	Date	Time	%BAC
Calibration	10/07/04	09:33	.100

Test Result

2001	01/05/07	02:13	.071
2002	01/05/07	02:14	.075
2003	01/09/07	02:31	.090
2004	01/09/07	02:33	.083
2005	01/09/07	02:56	.000
2006	01/10/07	04:44	.121
2007	01/10/07	04:46	.111
2008	01/11/07	11:48	.100

Push No. 3 to erase.
or power down to retain

STATE OF CALIFORNIA

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8508

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1202	34	06D1911510A2220	.100	21		.103			x		Parilla	17332	/

01/11/07 12:03
A94 Serial no: 008580
Version no: 4797

No. Date Time %BAC
Calibration
12/01/06 08:14 .099

Test Result
2001 01/11/07 12:02 .103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
South Los Angeles	530	Parilla	17332	Alco Sensor IV	68546

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1153	34	06D1911510A2220	.100	22		.103			✓		Parilla	17332	1

01/11/07 11:54
ASA Serial no: 000545
Version no: 4797

No.	Date	Time	%BAC
Calibration			
	04/22/04	07:47	.100

Test Result
0001 01/11/07 11:54 .103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8559

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1202	34	06D1911510A2220	.100	21		.104			X		Parilla	17332	26

01/11/07 12:04
AOA Serial no: 008559
Version no: 4797

No. Date Time %BAC
Calibration
10/25/05 07:58 .100

Test Result
0001 01/05/07 02:26 .170
0002 01/05/07 02:28 .173
0003 01/06/07 00:02 .161
0004 01/06/07 00:04 .164
0005 01/06/07 02:49 .078
0006 01/06/07 03:51 .076
0007 01/06/07 05:12 .002
0008 01/06/07 05:12 .000
0009 01/06/07 05:13 .000
0010 01/06/07 06:31 .139
0011 01/06/07 08:33 .112
0012 01/06/07 23:58 .148
0013 01/06/07 23:52 .141
0014 01/07/07 01:33 .097
0015 01/07/07 01:35 .117
0016 01/07/07 01:38 .109
0017 01/07/07 03:37 .000
0018 01/07/07 05:19 .056
0019 01/07/07 05:20 .049
0020 01/07/07 05:58 .219
0021 01/07/07 06:00 .295
0022 01/08/07 00:51 .046
0023 01/08/07 00:52 .049
0024 01/08/07 01:35 .142
0025 01/08/07 01:37 .178
0026 01/11/07 12:03 .104

Push b. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8620

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1214	34	06D1911510A2220	.100	21		.102			X		Parilla	17332	4

01/11/07 12:18
ASA Serial no: 008629
Version no: 4797

No.	Date	Time	%BAC
Calibration	05/26/05	09:25	.100

Test	Result		
0001	01/06/07	00:11	.008
0002	01/06/07	01:06	.108
0003	01/06/07	01:09	.106
0004	01/11/07	12:14	.102

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8635

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1300	34	06D1911510A2220	.100	22		.103			x		Parilla	17332	1

01/11/07 13:01
A84 Serial no: 008635
Version no: 4797

No. Date Time %BAC
Calibration
10/24/03 09:04 .100

Test Result
0001 01/11/07 13:01 .103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	ID NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8663

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1229	34	06D1911510A2220	.100	23		.103			X		Parilla	17332	8

01/11/07 12:28
884 Serial no: 008663
Version no: 4797

No.	Date	Time	AMOC
Calibration	12/21/04	11:26	.100

Test	Result		
0001	01/06/07	02:20	.069
0002	01/06/07	03:00	.078
0003	01/06/07	03:05	.081
0004	01/06/07	03:07	.089
0005	01/07/07	01:27	.056
0006	01/07/07	01:28	.050
0007	01/07/07	03:52	.000
0008	01/11/07	12:29	.103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I D NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8709

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I D NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1243	34	06D1911510A2220	.100	22		.103			X		Parilla	17332	2

01/11/07 12:44
AS4 Serial no: 008714
Version no: 4797

No. Date Time %BAC
Calibration
03/11/04 14:05 .100

Test Result
0001 01/08/07 00:35 .037
0002 01/11/07 12:43 .103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8714

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1239	34	06D1911510A2220	.100	22		.101			x		Parilla	17332	4

01/11/07 12:40
BAC Serial no: 008709
Version no: 4797

No.	Date	Time	%BAC
Calibration			
	05/26/04	11:06	.096

Test	Result		
0001	01/06/07	23:17	.000
0002	01/06/07	23:33	.000
0003	01/07/07	00:54	.000
0004	01/11/07	12:39	.101

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8783

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1243	34	06D1911510A2220	100	21		.08			X		Parilla	17332	13

01/11/07 12:44
AS4 Serial no: 008783
Version no: 4797

No. Date Time %BAC
Calibration
10/17/06 09:36 .102

Test Result
0001 01/06/07 00:43 .175
0002 01/06/07 01:07 .000
0003 01/06/07 01:59 .147
0004 01/06/07 02:01 .137
0005 01/06/07 23:15 .014
0006 01/07/07 00:00 .000
0007 01/07/07 00:59 .000
0008 01/07/07 01:47 .075
0009 01/07/07 01:48 .060
0010 01/07/07 03:07 .140
0011 01/07/07 03:09 .144
0012 01/07/07 22:27 .000
0013 01/11/07 12:44 .108

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8810

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1250	34	06D1911510A2220	.100	21		.099			<		Parilla	17332	

01/11/07 12:51
AS4 Serial no: 008810
Version no: 4797

No. Date Time %BAC
Calibration
10/30/03 09:53 .100

Test Result
0001 01/11/07 12:50 .099

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8848

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1248	34	06D1911510A2220	.100	22							Parilla	17332	5

01/11/07 12:50
A54 Serial no: 008848
Version no: 4797

No. Date Time %BAC
Calibration
01/13/03 09:25 .100

Test Result
0001 01/05/07 02:28 .085
0002 01/05/07 02:29 .089
0003 01/05/07 02:32 .155
0004 01/05/07 02:34 .000
0005 01/11/07 12:49 .102

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8850

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1302	34	06D1911510A2220	.100	22		.100			X		Parilla	17332	2

01/11/07 13:03
684 Serial no: 008850
Version no: 4797

No. Date Time ZBAC
Calibration
03/02/06 09:07 .100

Test Result
0001 01/06/07 00:45 .000
0002 01/11/07 13:03 .100

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8874

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1259	34	06D1911510A2220	100	22		.102			x		Parilla	17332	6

01/11/07 13:00
A84 Serial no: 008874
Version no: 4797

Ref.	Date	Time	%BAC
Calibration			
	11/04/04	08:49	.100

Test Result

0001	12/31/06	18:29	.000
0002	12/31/06	20:01	.147
0003	12/31/06	20:03	.142
0004	01/09/07	21:06	.181
0005	01/09/07	21:08	.177
0006	01/11/07	12:59	.102

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	8877

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1315	34	06D1911510A2220	.100	22		.101			X		Parilla	17332	3

01/11/07 13:16
PAS Serial no: 008877
Version no: 4797

No. Date Time %PAC
Calibration
05/26/05 10:40 .100

Test Result
0001 01/07/07 04:06 .025
0002 01/08/07 00:05 .064
0003 01/11/07 13:16 .101

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	17990

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1344	34	06D1911510A2220	.100	22		.104			X		Parilla	17332	/

01/11/07 13:45
ABA Serial no: 017990
Version no: 4797

No. Date Time %BAC
Calibration
11/26/03 11:18 .100

Test Result
0001 01/11/07 13:44 .104

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18622

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1330	34	06D1911510A2220	.100	22		.107			x		Parilla	17332	4

01/11/07 13:31
ASA Serial no: 018622
Version no: 4797

No. Date Time %BAC
Calibration
03/19/04 13:42 .100

Test Result
[illegible] 01/07/07 01:11 .010
[illegible] 01/08/07 22:52 .129
[illegible] 01/08/07 22:56 .123
[illegible] 01/11/07 13:30 .107

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO.
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18624

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1326	34	06D1911510A2220	.100	22		.108			X		Parilla	17332	1

01/11/07 13:27
#64 Serial no: 018624
Version no: 4797

No. Date Time %BAC
Calibration
05/01/03 05:38 .100

Test Result
0001 01/11/07 13:26 .108

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18684

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1353	34	06D1911510A2220	.100	23		.101			x		Parilla	17332	8

```
01/11/07 13:54
AS4 Serial no: 018684
Version    no: 4797

No.   Date     Time   %BAC
Calibration
      01/29/04 12:45 .100

Test Result
0001 01/05/07 01:22 .201
0002 01/05/07 01:23 .168
0003 01/05/07 01:25 .196
0004 01/06/07 01:17 .115
0005 01/06/07 03:28 .000
0006 01/11/07 01:55 .000
0007 01/11/07 02:24 .000
0008 01/11/07 13:54 .101

Push No. 3  to erase,
or power down to retain
```

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18691

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1256	34	06D1911510A2220	.100	23		.108			✓		Parilla	17332	1

01/11/07 12:57
A84 Serial no: 018691
Version no: 4797

No. Date Time %BAC
Calibration
01/28/06 03:44 .100

Test Result
0001 01/11/07 12:56 .108

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO.	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18692

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1330	34	06D1911510A2220	.100	22					✓		Parilla	17332	1

01/11/07 13:31
A94 Serial no: 018692
Version no: 4797

No. Date Time %BAC
Calibration
05/05/05 09:32 .100

Test Result
0001 01/11/07 13:31 .105

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18762

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1336	34	06D1911510A2220	.100	21		.104			x		Parilla	17332	1

01/11/07 13:37
A54 Serial no: 018762
Version no: 4797

No. Date Time %BAC
Calibration
03/11/04 15:53 .100

Test Result
0001 01/11/07 13:37 .104

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18766

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1332	34	06D1911510A2220	.100	22		.102			x		Parilla	17332	/

01/11/07 13:34
AS4 Serial no: 018766
Version no: 4797

No. Date Time %BAC
Calibration
12/09/02 09:55 .100

Test Result
0001 01/11/07 13:33 .102

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18774

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1337	34	06D19P1510A2220	.100	22		.101			X		Parilla	17332	1

01/11/07 13:38
A54 Serial no: 018774
Version no: 4797

No. Date Time %BAC
Calibration
06/01/06 16:42 .100

Test Result
R001 01/11/07 13:38 .101

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	ID NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	18785

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1151	34	06D1911510A2220	.100	21		.106			X		Parilla	17332	3

01/11/07 11:52
ASA Serial no: 018785
Version no: 4797

No.	Date	Time	%BAC
Calibration			
	11/08/05	09:34	.100

Test	Result		
0001	01/05/07	21:35	.272
0002	01/06/07	21:36	.268
0003	01/11/07	11:51	.106

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	ID NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	41486

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1358	34	06D1911510A2220	.100	22		.105			x		Parilla	17332	/

01/11/07 13:59
AS4 Serial no: 041486
Version no: 4797

No. Date Time PPAC
Calibration
02/08/06 13:56 .100

Test Result
0001 01/11/07 13:58 .105

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA

DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev. 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	41495

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO.	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1358	34	06D1911510A2220	.100	23		.098			X		Parilla	17332	9

01/11/07 14:00
AS4 Serial no: 041495
Version no: 4790

No.	Date	Time	ZPMC
Calibration	12/01/06	08:20	.059

Test	Result		
0001	01/06/07	00:55	.000
0002	01/06/07	02:28	.006
0003	01/06/07	02:49	.011
0004	01/06/07	02:50	.010
0005	01/06/07	03:24	.081
0006	01/06/07	03:25	.096
0007	01/06/07	00:24	.144
0008	01/06/07	02:26	.108
0009	01/11/07	14:00	.098

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	41502

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO.	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1402	34	06D1911510A2220	.100	21		.103			x		Parilla	17332	1

01/11/07 14:04
AS4 Serial no: 041502
Version no: 4797

No. Date Time %BAC
Calibration
11/02/05 15:31 .102

Test Result
0001 01/11/07 14:03 .103

Push No. 3 to erase,
or power down to retain

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

PRELIMINARY ALCOHOL SCREENING (PAS) DEVICE ACCURACY CHECK/CALIBRATION LOG

CHP 202K (Rev 9-98) OPI 051

AREA NAME	AREA NO	COORDINATOR NAME	I.D. NUMBER	PAS MAKE/MODEL	PAS SERIAL NO
South Los Angeles	530	Parilla	17332	Alco Sensor IV	41559

PAS DEVICES SHALL BE CHECKED FOR ACCURACY EVERY 10 DAYS OR EVERY 150 TESTS, WHICHEVER OCCURS FIRST.

DATE	TIME	SIMULATOR SOLUTION			PAS TEMP (°C)		PAS ACCURACY CHECK RESULTS*		CALIBRATION REQUIRED		PAS RETEST RESULTS	OPERATOR	I.D. NO	REPAIRS/PROBLEMS/ COMMENTS
		TEMP (°C)	LOT NO	VALUE	TEST #1	TEST #2 (Optional)	TEST #1	TEST #2 (Optional)	YES	NO				
01/11/2007	1405	34	06D1911510A2220	.100	21		.101			^		Parilla	17332	2

01/11/07 14:06
PAS Serial no: 041559
Version no: 4797

No. Date Time XBAC
Calibration
11/02/05 14:35 .102

Test Result
0001 01/06/07 23:43 .077
0002 01/11/07 14:06 .101

Push No. 3 to erase,
or power down to retain