

Channel View Park

Tree Removals - 2

Broken limb



The tree was trimmed to prevent removal. Work was unsuccessful due to broken limb and poor tree structure. Trunk shows advanced stages of anthracnose.



Old wound. Weak point in the limb. Potential hazard.



Trunk shows advanced stages of anthracnose. Base of the tree showing signs of decay.



Broken primary leader of the tree.



Broken primary leader of the tree. Dead limbs attached to primary leader would need to be removed. This would leave the tree unbalanced with a lot of weight on the right side over the walk path.



Trunk shows advanced signs of anthracnose. Trunk beginning to split.



Trunk shows advanced signs of anthracnose. Trunk beginning to split at the base of the tree.

